


90

.

200





in-line front-of-line portion 300A

V/C 302 V/C 302

D/A	cure	plasma	W/B	plasma
304	306	308	310	312

V/C 302

in-line end-of-line portion 300B

V/C	V/C
302	302

mold	PMC	SBA	saw	sort
314	316	318	320	322

in-line finish portion 300C

V/C	V/C	V/C
302	302	302

mark	FVI	T/R
324	326	328




Figure 4




Figure 5





FIGURE 6






FIGURE 8




FIGURE 9




FIGURE 10




FIGURE 11




FIGURE 12

